

January 12, 2022

Keystone Sanitary Landfill, Inc. c/o Mr. Dominic DeNaples Jr, Site Manager 249 Dunham Drive Dunmore, PA 18512

Email: dominickd@kslco.com

Re: Engineer's Monthly Status Report

Keystone Sanitary Landfill, Inc.

Throop/Dunmore Boroughs, Lackawanna County

I.D. No. 101247

Dear Mr. DeNaples:

This Engineer's Status Report is for the month of December 2021. Date of inspection — Wednesday January 12, 2022. This report is informational only, without deadlines, and a response is required only if objections are taken to the items mentioned. COVID-19 safety protocols were followed during the entire site visit.

# A. Pending Permit Applications:

1. Major Permit Modification – Phase III Development:

The major permit modification was approved on June 3, 2021.

- 2. Application for a major permit modification for a change in leachate treatment method (25 Pa Code §273.272) was received on December 18, 2019.

  This application was withdrawn on October 06, 2021. KSL plan to submit a revised new application at a later date.
- 3. Application for a minor permit modification for the installation of a chiller unit at the leachate plant was received by the Department on October 18, 2021. The application is currently under review.
- 4. Application for a minor permit modification to the Phase II stormwater management controls was received on October 18, 2021. The application was approved on December 28, 2021.

### **B.** Construction Activities:

1. KSL was placing waste mainly on Pad 11 and Pad 12 on the day of this inspection.

# 2. Pad 12:

Construction of Pad 12 is partially complete (STA 45+50 thru STA 48+00). A Form 37 construction certification for the completed section was received by the Department on June 29, 2021. The certification was approved on July 13, 2021.

## 3. Closure Work:

2020: KSL installed approximately 15 acres of temporary liner in 2020.

2021: as of June 9, 2021, KSL have installation 4.6 acres of final cap and 17.3 acres of temporary cap.

2022: KSL will be installing approximately 30 acres of final closure cap in Phase II.

4. Construction activities on the leachate conveyance system upgrade continues.

# C. Groundwater

1. There are thirty-six (36) approved ground water monitoring wells at the facility. All wells are sampled quarterly.

Second quarter groundwater sampling was completed in May 2021. Third quarter sampling was completed in second week of August 2021. Fourth quarter sampling was completed in November 2021. Next sampling event is scheduled for week of February 7, 2022.

### D. Leachate Treatment:

- 1. Estimated volume of leachate in lagoon storage as of 1/10/2022 approximately 3,012,161 gallons. Regulatory 25% storage capacity is 2,428,720 gallons.
- 2. KSL hauls leachate to the following offsite treatment facilities as needed:
  - a. Passaic Valley Sewage Commission in Newark, NJ.
  - b. Altoona Industrial Pre-treatment Facility

Leachate hauled off site in the month of December 2021 - 3,390,416 gallons.

3. Rainfall total for November 2021 – 1.41 inches.

# E. Gas Management:

1. The Department received an application for beneficial use (WMGM055) of the facility's LFG on July 13, 2021. The applicant – Assai Energy LLC. The application review is complete. The Department is waiting for Bonding Certification from the applicant before issuing the permit.

The application was approved and emailed to the applicant on January 6, 2022.

- 2. Unused LFG is being flared.
- 3. The stone columns and vacuum control devices are continually extended in the active portions of the landfill to ensure effective odor control.

# F. Site Observations

- 1. Litter observed crew picking litter along the road leading up to the working face. Portable fences were deployed at the working face.
- 2. Odor slight odor was perceived by the western slope of Pad 12; one of the stone columns was being adjusted/raised at the time.
- 3. Daily cover observed stockpile of cover materials by the crusher.

# G. Miscellaneous

- 1. Enclosed as part of this report is the monthly update sheet from Keystone Sanitary Landfill. Included is information on the site, radiation monitoring, truck safety and leachate management.
- 2. KSL performs daily routine odor patrols on-site and off-site, including Swinick Development, and Mid-Valley School District.
- 3. KSL has contracted the USDA Wild Life Services of PA to conduct on-site tests to determine the most effective migratory bird infestation control method for the landfill. The USDA submits quarterly report of its findings to KSL.
- 4. KSL continues to perform annual maintenance on all stormwater sedimentation basins removal of overgrown vegetation and repairs of shoreline erosion.

If you have any questions concerning this report, please contact me at (570) 826-2022, or nswarmate@pa.gov.

Sincerely,

### nswarmatc

N. Sam Warmate Waste Management Program

# Enclosure

cc: Dunmore Borough Manager (w/enc.)

Email: Vito.Ruggiero@DunmorePa.gov

Ms. Robin Galli, Secretary/Throop Borough (w/enc.)

Email: lcimini@throopboro.com

# PADEP Monthly Engineer's Status Report Reporting Period: December 2021

Keystone Sanitary Landfill, Inc.	249 Dunham Drive, Dunmore, PA 18512	570-343-5782	De 144 4040 44
Keyst	249 DI	570-34	Present.

General Site Information					Permit# 101247		
Ave Daily Volume For The							
Month of December 2021	6,163						
Maximum Permitted							
Daily Volume	7,500 Tons				Recorder Rainfall	1.41	
Maximum Permitted	88						
Quarterly Average/Day	7,250 Tons				53		
Active/Closed Areas	Total Acres	Final Cap	Temporary Cap Not Capped	Not Capped		Report Dates	
Keystone/Dunmore	105.73	105.73	0	0	32	Groundwater	10/15/2002
Logan	50.3	50.3	0	0		Air Monitoring	7/26/2021
Tabor	104	104	0	0		Gas	10/20/2021
Phase II	169.62	93.03	53.1	76.59			
Total Permitted Area	429.65		Leachate Management	gement			
Acreage Under Construction			Biological TreatmentCapacity	nentCapacity	150,000 GPD	GPD	
Phase II	0		R/O Treatment Capacity	Sapacity	90,000 GPD	GPD	
Phase III (Pads 1 & 2)	18.97		Total Plant Operating Capacity	ating Capacity	240,000 GPD	GPD	
			Total Leachate Generated	Senerated	6.649,399	6.649.399 Report Period	
Radiation Activity			Ave Daily Generated	erated	214,497	20	
Trucks That Tripped Monitor	3		Total Leachate Treated	reated	3,639,822	3,639,822 Report Period	
Trucks Rejected	0		Treated Effluent to PA Amer	to PA Amer.	3,639,822	3,639,822 Report Period	
Loads Identified As Tenorm	0						
Year To Date Tenorm							
			Average Daily Flow	OW.	117,414		
Truck Safety/Overweights			Leachate Hauled Off-Site	i Off-Site	3,390,416	3,390,416 Report Period	
73,280 to 80,000	71		Total Influent Storage Capacity	orage Capacity	9,714,881 Gallons	Gallons	
80,001 to 82,500	586		25% of Capacity		2,428,720 Gallons	Gallons	
82,501 to 85,000	400		Current Waste Water Stored	Water Stored	Gallons		
85,001 to 90,000	528		As of:	East	West	Total	
90,001 and Over	3		1/3/2022	1,233,757	2,206,009	3,439,766	
Total Overweight Trucks	1588		As of:	East	West	Total	
			1/10/2022	1,674,092	1,338,069	3.012.161	